



Ground Zero Electrostatics PMK-151 Resistance System Kit

PMK-151 Resistance System Kit Resistance Measurements With Computer Download Capabilities



Item Number
PMK-151

Contents

- ☼ PHT-770 Hygro-Thermometer
- ☼ GAP-005 Ground Adapter Plug
- ☼ Small Pony Clamp 3"
- ☼ Large Pony Clamp 6"
- ☼ PWS-610M Wrist Straps (2)
- ☼ PRS-800CS Cable Spacers Set - 36" & 10"
- ☼ PRS-801-W 5 lbs Conductive Rubber Electrodes (2)
- ☼ PRS-801 Instrument Set
- ☼ PRS-801-W 5 lbs Conductive Rubber Electrodes (2)
- ☼ PAB-023 Accessories Box
- ☼ PMK-151 Carrying Case with Handle

Options:

- ☼ PFK-100 Instrument Set
- ☼ PGT-61-154 SureTest® Circuit Analyzer
- ☼ PFM-711A Field Meter w/Analog output cable
- ☼ PWA-805 Wrist Strap Auditor
- ☼ PFA-860 Footwear Auditor
- ☼ PSI-870 Surface Resistance/Resistivity Indicator
- ☼ PRF-911 Concentric Ring Set
- ☼ PRF-912 Miniature Concentric Ring Micro Probe
- ☼ PRF-914 High Resistance Miniature Concentric Ring Micro Probe
- ☼ PRF-922 Miniature Two-Point Micro Probe

The PMK-151 Basic Measurement Kit has all the functionality of the PMK-152, but adds computer downloading capabilities. It contains all the instruments you need to take a variety of resistance measurements.

The PMK-151 includes PROSTAT's PRS-801 Resistance Set with modified 5 pound conductive rubber electrodes, the PRS-801 wide range resistance meter, and PROSTAT PRS-801 Connectivity software for computer data downloading. You can take measurements at 10 and 100 volts with accuracy within $\pm 5\%$.

To measure temperature and humidity, the PROSTAT PHT-770 Hygro-Thermometer is also included.

The PMK-151 comes with PROSTAT's unique 10" and 36" electrode spacers, a ground adapter plug, operator's manual, clamps and a variety of useful accessories. It's all self-contained in a sturdy carrying case. The PMK-151 is the most flexible kit available for your general auditing needs. You may customize the PMK-151 by adding various options.

Applications

- ☼ Take basic resistance measurements
- ☼ Measure resistance to ground
- ☼ Measure resistance point to point
- ☼ Measure temperature and relative humidity
- ☼ Measure worksurfaces, equipment, garments, furniture and flooring
- ☼ Download data to your Excel spreadsheet

Test According To

ESD S2.1 Garments
ESD S4.1 Worksurfaces
ANSI/ESDS7.1 Flooring
ESD S12.1 Seating

Packaging

Weight: 23 lbs (10.5 kg)
Length: 18.5 Inches (48 cm)
Width: 7.5 Inches (19 cm)
Height: 16 Inches (40 cm)

