



PMK-152 Advanced Resistance Kit

General Auditing and Resistance Measurements



Item Number
PMK-152

Contents

- ☼ PHT-770 Hygro-Thermometer
- ☼ GAP-005 Ground Adapter Plug Large
- ☼ Pony Clamp 3" Large
- ☼ Pony Clamp 6"
- ☼ PWS-610M Wrist Straps (2)
- ☼ PRS-812 Instrument Set
- ☼ Operator's Manual
- ☼ PAB-023 Accessories Box
- ☼ PMK-151 Carrying Case with Handles

Options:

- ☼ PFK-100 Instrument Set
- ☼ PGT-61-154 SureTest® Circuit Analyzer
- ☼ PFM-711A Field Meter w/Analog output cable
- ☼ PWA-805 Wrist Strap Auditor
- ☼ PFA-860 Footwear Auditor
- ☼ PSI-870 Surface Resistance/Resistivity Indicator
- ☼ PRF-911 Concentric Ring Set
- ☼ PRF-912 Miniature Concentric Ring Micro Probe
- ☼ PRF-914 High Resistance Miniature Concentric Ring Micro Probe
- ☼ PRF-922 Miniature Two-Point Micro Probe

The PMK-152 Advanced Resistance Kit contains the instruments you need to take resistance measurements.

The PMK-152 includes PROSTAT's PRS-812 Resistance Meter with 5 pound conductive rubber electrodes. You can take measurements at 10 and 100 volts with accuracy within $\pm 5\%$.

To measure temperature and humidity, the PROSTAT PHT-770 Hygro-Thermometer is also included.

The PMK-152 comes with PROSTAT's unique 10" and 36" electrode spacers, a ground adapter plug, operator's manual, clamps and a variety of useful accessories. It's all self-contained in a sturdy carrying case. The PMK-152 is highly flexible for your general auditing needs. You may customize the PMK-152 by adding various options.

Applications

- ☼ Take basic resistance measurements
- ☼ Measure resistance to ground
- ☼ Measure resistance point to point
- ☼ Measure temperature and relative humidity
- ☼ Measure worksurfaces, equipment, garments, furniture and flooring

Test According To

ESD S2.1 Garments
ESD S4.1 Worksurfaces
ANSI/ESDS7.1 Flooring
ESD S12.1 Seating

Packaging

Weight: 23 lbs (10.5 kg)
Length: 18.5 Inches (47 cm)
Width: 7.5 Inches (19 cm)
Height: 16 Inches (40 cm)

